

Customer: CFG

Type: A318/A319/A320/A321

Rev. Date: Aug 01/12

Manual: TSM Selected effectivity: ALL

## 28-00-00-810-801-A - Fuel Smell In Cabin

# **Fault Symptoms**

** ON A/C ALL			28-00-00-810-801-A
Wa	rnings/mal	unctions	
	ATA	Message	
<	28-00	CABIN AIR SMELLS OF FUEL	

## Isolation Procedure

\*\* ON A/C ALL

TASK 28-00-00-810-801-A Fuel Smell In Cabin

WARNING: OBEY THE FUEL SAFETY PROCEDURES.

1. Possible Causes

- a fuel leak found below the cabin floor at the left (right) side of the fuselage frame 36/wing rib 1 intersection

2. Job Set-up Information

A. Referenced Information

#### REFERENCE

#### DESIGNATION

AMM 21-20-00-010-001 Removal of the Air-Conditioning Distribution Ducts

AMM 21-20-00-410-001 Installation of the Air-Conditioning Distribution Ducts

AMM 21-21-41-000-001 Removal of the Recirculation Filter

AMM 21-21-41-400-001 Installation of the Recirculation Filter

AMM 28-11-00-280-002 Structural Fuel Tank Leaks - General Information

AMM 53-32-12-000-002 Removal of the Cabin Floor Panels

AMM 53-32-12-400-002 Installation of the Cabin Floor Panels

SIL 57-086

SIL 57-091

SRM 571600

#### 3. Fault Confirmation

Subtask 28-00-00-210-050-A

#### A. Inspection/Test

- (1) Do a visual inspection/leak test to locate a possible fuel leak as follows:
  - (a) Remove the necessary equipment and furnishing to get access to the cabin floor panels 241HF and 242HF (center passenger compartment).
  - (b) Remove the cabin floor panels 241HF and 242HF (located between frames 36 and 42) AMM 53-32-12-000-002.
  - (c) Remove the applicable air conditioning ducts, from above the wing box center section, in the area adjacent to:
    - the intersection between the left side of the fuselage frame 36 and the left wing rib 1
    - the intersection between the right side of the fuselage frame 36 and the right wing rib 1 AMM 21-20-00-010-001.
  - (d) Release and carefully pull back the applicable insulation mats/blankets in the area specified in Step (c).
  - (e) Examine for indications of a fuel leak at:
    - the intersection between the left side of the fuselage frame 36 (rear face) and the left wing rib

Print Date: Sep 10/12 Local Time

Page 1 of 3



Customer: CFG

Type: A318/A319/A320/A321

Rev. Date: Aug 01/12

Manual: TSM Selected effectivity: ALL

28-00-00-810-801-A - Fuel Smell In Cabin

1

- the intersection between the right side of the fuselage frame 36 (rear face) and the right wing rib 1.
- (f) If necessary, do a leak test in the area around the sealing brackets SRM 571600, Figure 2 (Sheet 1), item 10.

Use one of the applicable procedures as follows:

- Fuel Tank Leak Checks AMM 28-11-00-280-002
- Fuel Leak Test Source Detection, Helium Method SIL 57-091.
- (g) Examine all the insulation mats/blankets:
  - in and adjacent to the leak area specified in Step (c)
  - on the pressurized panel between the frames 35 and 36.
- (h) Remove and discard any insulation mats/blankets contaminated with fuel.

## 4. Fault Isolation

Subtask 28-00-00-810-050-A

## A. Procedure

- (1) For a fuel leak found below the cabin floor at the left (right) side of the fuselage frame 36/wing rib 1 intersection , the options available are as follows:
  - (a) Ferry Flight

A ferry flight for the aircraft to return to its main base (without repair) is allowed.

- 1 Remove the fuel that has leaked.
- 2 Clean the work area.
- 3 The cabin fans must be set to on during the ferry flight.
- (b) Temporary Repair
  - 1 Use fast curing sealant as detailed in SIL 57-086, Part A, to do a temporary repair.
  - 2 Make an entry in the aircraft technical log to record the temporary repair to this fuel leak.

NOTE: A temporary repair is limited/valid for 50 flying hours before a final repair has to be carried out.

- (c) Final Repair
  - 1 Do a final repair as follows:
    - a You must read repair instructions SIL 57-086 Part A and Part B before you do the repair.
    - b Do the FUEL LEAK REPAIR TECHNICAL SHEET R571.12107.
  - 2 On completion of the repair:
    - replace the two (2) air recirculation filters (4012HM) and (4013HM), <u>AMM 21-21-41-000-001</u> and AMM 21-21-41-400-001.
- (2) If a Temporary or Final Repair is done:
  - replace, as necessary, any fuel contaminated insulation mats/blankets found in Para. 3.

#### 5. Close-up

Subtask 28-00-00-942-050-A

# A. Close Access

- (1) Make sure the work area is clean, clear of tool(s) and other items.
- (2) Install the new, or, release, fold down and attach in their initial positions the original insulation mats/blankets.
- (3) Install the cabin air supply ducts AMM 21-20-00-410-001.
- (4) Install the cabin floor panels 241HF and 242HF AMM 53-32-12-400-002.

Print Date: Sep 10/12 Local Time

Page 2 of 3



Customer: CFG

Type: A318/A319/A320/A321

Rev. Date: Aug 01/12

Manual: TSM Selected effectivity: ALL

28-00-00-810-801-A - Fuel Smell In Cabin

(5) Install the equipment and furnishing, removed to get access to the cabin floor panels 241HF and 242HF.

(6) Remove the ground support and maintenance equipment, the special and standard tools and all other items.

Print Date: Sep 10/12 Local Time

Page 3 of 3